Old Cleyton House Smyrna, Delaware HABSNo. Del- 122

HASS DEL

1- SMYR

2. -

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
District of Delaware

ADDENDUM FOLLOWS...

Historic American Buildings Survey Weston H. Blake, District Officer 909 West Street, Wilmington, Delaware

DEL.

1- SMYR

OLD CLAYTON HOUSE Smyrna, Kent County, Delaware.

2-

Owner: Miss Mary Spruance.

Present Condition: Good, but with many modern additions out of character with the briginal style, (porches in particular).

Number of Stories: Two and a half.

Materials of Construction: Brick walls and chimneys, shingle roof, wooden framing and floors, cornices and trim.

Other Existing Records: Office of Recorder of Deeds, Kent County, Dover, Delaware.

Additional Data: The original late colonial home has very good woodwork, staircase, fireplaces, door, trim and cornices on the intermor and outside cornices and dormers. The modern excrescences are unfortunate, but the north east end has some unusual treatments which would be extremely interesting if in style.

Laussat R. Rogers

Approved Hestin 413

District Officer

Addendum to:
Enoch Spruance House (Old Clayton House)
117 East Commerce Street
Smyrna
Kent County
Delaware

HABS No. DE-122

HABS DEL, I-SMYR, 2-

PHOTOGRAPHS

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106